

## WAX AND GREASE REMOVER

1. Wash the surface with water and a mild-detergent soap, rinse thoroughly and let dry. Use Wax & Grease Remover to remove silicone, wax, oil and grease.
2. Pour into a 4 fl oz Hand-Held Spray bottle. Spray surface liberally with Wax and Grease Remover Solvent from hand held spray bottle.
3. Wipe dry while the surface is still wet.
4. Always wipe dry in the same direction, changing cloths as one cloth will merely shift rather than remove grease.

**CAUTION:** THIS PRODUCT IS NOT RECOMMENDED FOR USE ON PLASTIC OR FIBREGLASS, OVER FRESHLY PAINTED SURFACES OR OVER FRESH PRIMERS-SEALERS. SOAKED WIPERS SHOULD NOT BE ALLOWED TO REMAIN ON FINISHED SURFACES. – DISPOSE OF CLOTH SAFELY TO AVOID RISK OF SPONTANEOUS COMBUSTION FIRE.